



15-045397

<p>Work Order</p> <p>15-045397</p> <p>Status: READY TO CLOSE</p>

Work Order Assignment Report

Work Order			
Description:	REPAIR AC UNIT IN ROOM 101	Created By:	SSTERNER
		Date Created:	Jun 23, 2015, 12:16 PM
		Desired Date:	
		Customer Request:	197135
Type:	MAINTENANCE (MAINTENANCE)	Category:	CORRECTIVE (Repair failure)
Project:		Problem Code:	
Organization			
Organization:	F00750 (BIO SECURITY AND FOOD SAFETY CENTER)		
Requestor:	BIO SECURITY AND FOOD SAF (null)		
Contact:	CHARLEY DAVIS		
Contact Email:	chardavi@nmsu.edu	Contact Phone:	644-4391
Property			
Region:	NMSU (NEW MEXICO STATE UNIVERSITY)	Facility:	LAS CRUCES (LAS CRUCES)
Property:	367 (VERLOFFICE/LAB)		
Shop			
Shop Person:		Shop:	MECHANICAL (F00471: MECHANICAL SHOP (FORMERLY HVAC/ MECH))

Phase Assignment

001

<p>Phase</p> <p>001</p> <p>Status: WORK COMPLETE</p>

Phase			
Description:	REPAIR AC UNIT IN ROOM 101	Created By:	SSTERNER
		Date Created:	Jun 23, 2015, 12:16 PM
		Estimated Start:	
		Estimated End:	
Location:	101 (CAHFS LIVESTOCK INSECT LAB PREP)	Priority:	3-ROUTINE
Shop:	MECHANICAL (F00471: MECHANICAL SHOP (FORMERLY HVAC/MECH))	Funding Source:	Shop
Work Code:	D3000	Work Code Group:	UTILITIES (HVAC: ALL HEATING, VENTILATION AND AIR CONDITIONING PROBLEMS IN A BUILDING INCLUDES T-STATS)
Equipment			
Equipment:		Equipment Group:	
Asset Tag:		Asset Type:	
Contractor			
Contractor:		Contract Type:	
Phone:		Contract #:	
Address:			

Shop Assignments

Shop Person:	FERNCANA (FERNANDO CANALES)	*FERNCANA*			
Primary:				Certified:	No
Assigned By:	CATANACH			Assigned Date:	Jun 26, 2015

Other

Extra Descriptions

Work Order Extra Description:	
Phase Extra Description:	



15-045397

Work Order 15-045397 Status: READY TO CLOSE

Work Order Assignment Report

Work Order			
Description:	REPAIR AC UNIT IN ROOM 101	Created By:	SSTERNER
		Date Created:	Jun 23, 2015, 12:16 PM
		Desired Date:	
		Customer Request:	197135
Type:	MAINTENANCE (MAINTENANCE)	Category:	CORRECTIVE (Repair failure)
Project:		Problem Code:	
Organization			
Organization:	F00750 (BIO SECURITY AND FOOD SAFETY CENTER)		
Requestor:	BIO SECURITY AND FOOD SAF (null)		
Contact:	CHARLEY DAVIS		
Contact Email:	chardavi@nmsu.edu	Contact Phone:	644-4391
Property			
Region:	NMSU (NEW MEXICO STATE UNIVERSITY)	Facility:	LAS CRUCES (LAS CRUCES)
Property:	367 (VERLOFFICE/LAB)		
Shop			
Shop Person:		Shop:	MECHANICAL (F00471: MECHANICAL SHOP (FORMERLY HVAC/ MECH))

Phase Assignment

002

Phase 002 Status: WORK COMPLETE

Phase			
Description:	PLEASE INSTALL A NEW DISCONNECT FOR THE NEW AC UNIT, AND INSTALL NEW POWER SUPPLY TO IT.	Created By:	FERNCANANA
		Date Created:	Sep 28, 2015, 5:03 PM
		Estimated Start:	Oct 5, 2015
		Estimated End:	
Location:		Priority:	3-ROUTINE
Shop:	ELECTRIC (F00461:ELECTRIC SHOP)	Funding Source:	Shop
Work Code:	D5000	Work Code Group:	UTILITIES (ELECTRICAL)
Equipment			
Equipment:		Equipment Group:	
Asset Tag:		Asset Type:	
Contractor			
Contractor:		Contract Type:	
Phone:		Contract #:	
Address:			
Shop Assignments			

Shop Person:	DAVEROOT (DAVID ROOT)		*DAVEROOT*
Primary:		Certified: No	
Assigned By:	MLUCHAU	Assigned Date: Sep 30, 2015	

Other

Extra Descriptions	
Work Order Extra Description:	
Phase Extra Description:	

Notes Log

Phase: **001** Created By: **SSTERNER**
 Date Created: **Jun 23, 2015 12:16 PM**

Description: REPAIR AC UNIT IN ROOM 101

Add to Main Workdesk: No
 Add to Module Workdesk: No
 Note Type:
 Channel Title:

Notes Log

From: To: contains

Edit Date	Editor	Name	Note Type	Notes
Oct 02, 2015 05:08 PM	FERNCANA	FERNANDO CANALES		TIMECARD:423724 ITEM:1 STARTED UP, AND TESTED NEW DUCTLESS HEAT PUMP. WORK COMPLETE.
Sep 30, 2015 04:01 PM	GIANCARL	JOSE BARAJAS		TIMECARD:423059 ITEM:4 ASSISTED FERNANDO CANALES.
Sep 29, 2015 04:53 PM	FERNCANA	FERNANDO CANALES		TIMECARD:422765 ITEM:1 CONTINUED WITH THE MINISPLIT INSTALLATION. NEED NEW ELECTRICAL WORK FOR STAR UP.
Sep 28, 2015 05:03 PM	FERNCANA	FERNANDO CANALES		TIMECARD:422436 ITEM:1 REMOVED OLD MINI SPLIT AND PIPING, AND BEGAN INSTALLATION OF NEW MINI SPLIT.
Jul 15, 2015 07:47 AM	FERNCANA	FERNANDO CANALES		TIMECARD:405523 ITEM:1 TROUBLESHOOT SYSTEM WITH THE ASSISTANCE OF THE MANUFACTURER'S TECHNICAL SUPPORT. WE FOUND THAT WE HAVE AN INCORRECT TRANSFORMER ON THE UNIT AND THAT MORE THAN LIKELY THE OUTDOOR MAIN BOARD IS DAMAGED. THE TRANSFORMER FOR THE SYSTEM IS NO LONGER AVAILABLE.
Jul 13, 2015 08:20 AM	GIANCARL	JOSE BARAJAS		TIMECARD:404749 ITEM:6 ASSISTED FERNANDO CANALES IN TROUBLE SHOOTING A UNIT.
Jul 10, 2015 05:25 PM	FERNCANA	FERNANDO CANALES		TIMECARD:404649 ITEM:2 INSTALLED A NEW DISPLAY PCB AND A MAIN PCB. THE SYSTEM WAS NOT RESPONSIVE. ATTEMPTED TO CONTACT TECH SUPPORT BUT TO NO AVAIL. I WILL LOOK INTO REPLACING THE ENTIRE UNIT. WORK COMPLETE.
Jul 01, 2015 04:59 PM	FERNCANA	FERNANDO CANALES		TIMECARD:402377 ITEM:3 SHOPPED FOR PARTS, AND PLACED MATERIAL REQUEST FOR PARTS.
Jun 29, 2015 05:39 PM	FERNCANA	FERNANDO CANALES		TIMECARD:401743 ITEM:5 SEARCHED FOR PARTS. I CURRENTLY HAVE JOHNSTONE SUPPLY LOOKING FOR THE REPAIR PARTS.
Jun 26, 2015 05:26 PM	FERNCANA	FERNANDO CANALES		TIMECARD:401399 ITEM:6 TROUBLESHOOT MINI SPLIT. OUT DOOR UNIT OPERATIONAL. I FOUND THAT THE INDOOR UNIT DOES NOT BECAUSE THE RECEIVER BECAME DAMAGED, PROBABLY WITH CONDENSATE WATER. THE INDOOR UNIT'S CONTROLLER ALSO SHOWS SOME DAMAGE. I SEARCHED FOR PARTS ONLINE BUT IT SEEM TO BE OBSOLETE. WE MIGHT NEED A NEW MINI SPLIT.